## Safety Soapbox

## Absolute shocker of the week

17 December 2013

Work Safe





More information on working at heights safely see Compliance Code - Prevention of falls in general construction

Absolute shocker of the week is published by WorkSafe Victoria to promote safer work practices in construction, utilities, mining and quarrying. It may be freely copied for such purposes.

For more information, go to worksafe.vic.gov.au

incomplete,

fitted under the roof,

• the roof safety mesh has not been installed, nor are there safety nets

they have not even attached their

safety harnesses to the roof structure to provide fall arrest.

To get on the roof they have broken the golden rule of elevating work platform (EWP) use; NEVER get out of the EWP basket when elevated.

Access to this type of roof should be via a scaffold stair access tower.

